



AN ALTERNATIVE TO
 MACHINING THE GROOVE
 IS TO MOVE THE WINCH
 AFT AND RUN THE
 WIRE FROM THE BOTTOM
 OF THE BOARD. THIS
 IS AN INTRINSICALLY
 SAFER RIG : EASIER TO
 RAISE AND PUTTING LESS
 STRAIN ON THE HINGE
 PIN.

7/7/81
 #2