

SANTANA 21 KEEL REPLACEMENT


The Santana 21 was built with two different swing keels. The differences were in the shape of the top portion of the keel, in the type of block and tackle apparatus used in raising and lowering the keel, and in the style of centerboard well and cabinetry in the cabin.

Drawings of the two centerboard styles are attached. The best way to determine which style was used in your boat is to identify the interior centerboard trunk.


Replacement Santana 21 centerboards are available through the W. D. Schock Corporation. Since we no longer have these boards in stock, they must be special ordered. A lead time of approximately 6 weeks is required.

C A U T I O N

For your convenience, the Santana 21 has a very powerful keel winch. If the winch is force operated after the keel is fully retracted, damage will occur to either the winch or the keel block. OPERATE THE WINCH SLOWLY. DO NOT USE FORCE.



SANTANA 39



SANTANA 35



SANTANA 30




SANTANA 228



SANTANA 525



SANTANA 23



SANTANA 20



LIDO 14



CAPRI